



**REQUIRED CLOTHING, SAFETY EQUIPMENT, WELDING EQUIPMENT AND  
TOOLS FOR OXYACETYLENE WELDING AND WELDING CERTIFICATION  
PREPARATION**

**\*All items can be purchased at Harbor Freight or Awisco\***

**CLOTHING:**

High top boots  
Long pants (Denim or Cotton) no cuffs, no holes or frays  
Long sleeved shirts (Cotton or Wool)  
Welding hat or baseball cap  
Welding gloves

**SAFETY EQUIPMENT:**

Safety glasses with side shields  
Leather welding jacket or sleeves  
Ear protection for grinding  
Goggles with #5 shade lenses

**WELDING EQUIPMENT:**

Welding hood with #10-#12 shade lenses depending on sensitivity to eyes  
Chipping hammer  
Wire brush  
Ball peen hammer  
Chisel  
Soapstone  
Striker

**TOOLS:**

Slip-joint pliers  
Adjustable wrench